

For customers using the Cutting Blade Holder PHP33-CB09-HS

Please be advised the following issue regarding the Cutting Blade Holder “PHP33-CB09-HS” attached to the CE6000 series and the FC8600 series as the standard accessory and provided as the supplies.

We have found that the cap portion of the blade holder “PHP33-CB09-HS” may be damaged.

We would ask that you please check the cutting blade holder attached as standard accessory according to the following procedure after you have opened the box of the CE6000, FC8600, or the PHP33-CB09-HS.

The damage occurs when you install a cutting blade to the blade holder at the first time, or immediately after unsealing it.

There is no problem for the cutting blade holder that has been used already.

If it occurs, please contact to your local representative of Graphtec who provide the CE6000, FC8600, or the PHP33-CB09-HS to you. We will provide the replacement in free of charge through your local representative of Graphtec.


We would ask that please you report the manufacturing lot-number of the cutting blade holder when you find the damage.

< Corresponding model >

- CE6000 series and FC8600 series (PHP33-CB09-HS is attached as the standard accessory),
- PHP33-CB09-HS that is provided as the supplies

Procedure of checking the PHP33-CB09-HS blade holder


Please check the PHP33-CB09-HS blade holder when you use it the first time. Before mounting the cutter blade, the cap of the blade holder is installed to the body of the blade holder. The cap is turned in a clockwise until it stops for it. When you apply a force to turn further clockwise from the position stopped, it will be damaged if it has the problem.



Damaged cutter blade holder



Manufacturing Lot-number



The lot-number is shown in the package and the blade holder. Those are shown above. Number is the following.
"One (1) digit of alphabet & four (4) digits of numbers"